

Inside Tasks

- Fabricate 50 kick switch kits
- Fabricate 100 switch bar mechanisms
 - This is the F shaped piece made from 1/8"x1" steel
- Weld up 120 insulated track joiners Clips
- Fabricate 400 insulated track joiner plastic bars
- Make 80 Safety chains for flat cars
- Assemble 10,000 Plastic Nails

Outside Tasks

- Switch Stand at S Switch Crane
- Switch Stand at Entry to Yard from Hope Circle
- Switch Stand at turn off to Panzik from Hope Circle
 - Rod for this stand is in the bush just NE of switch
- Connect the Spur track panels at Witcombe Wye and Ballast
- Kick Mechanisms
 - 4 Yard Switches at Hope
 - 3 Wye Switches at Hope
 - Spur Switch at Crane
 - N switch Crane Siding
 - Cooper Junction just north of Schubert
- Clean up spilled gravel at load site N of Crane Road Crossing
- Clean up Trash on the hill SW of Schubert